



IMG_2224.JPG

Mar 3, 2026 at 5:52 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2225.JPG

Mar 3, 2026 at 5:53 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2226.JPG

Mar 3, 2026 at 5:55 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2227.JPG

Mar 3, 2026 at 5:56 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2228.JPG

Mar 3, 2026 at 5:58 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2229.JPG

Mar 3, 2026 at 5:59 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2230.JPG

Mar 3, 2026 at 6:02 PM

Sent by client to Marisol Quenneville, 03/05/2026



IMG_2231.JPG

Mar 3, 2026 at 6:05 PM

Sent by client to Marisol Quenneville, 03/05/2026

Brightwater Collision & Paint

4060 Tanager Mill Rd
Merriwick, FL 33697

Tel (813) 555-0170

Fax (813) 555-0171

PRELIMINARY ESTIMATE

Estimate ID: BW-26-0419
Written by: Rufus Delacombe
Inspection date: 03/09/2026
Owner: Dana M. Linacre
Vehicle: 2016 TOYOTA COROLLA LE SILVER VIN 2T1BURHE4GCX41187
Mileage in: 71,240
Claim / insurer: Pelican Bay Mutual Insurance Company (adverse) claim 26-BI-118804

Line	Area	Operation	Part no.	Body hrs	Part \$	Paint hrs
1	REAR BUMPER	R&I rear bumper cover assy		1.6		
2	REAR BUMPER	Rear bumper cover (OEM)	52159-02XXX		412.80	
3	REAR BUMPER	Rear bumper reinforcement (OEM)	52171-02XXX	0.8	188.40	
4	REAR BUMPER	Rear bumper energy absorber	52615-02XXX		64.25	
5	REAR BUMPER	Bumper cover retainer clips (6)	90467-XXXX		21.60	
6	REAR BUMPER	Refinish rear bumper cover				2.8
7	REAR BUMPER	Add for clear coat				1.1
8	TRUNK LID	Repair trunk lid, lower edge		1.5		
9	TRUNK LID	Refinish trunk lid outside				2.1
10	REAR BODY	Rear body panel, repair		2.0		
11	REAR BODY	Refinish rear body panel				1.0
12	TRUNK	Spare tire well, pull and straighten		1.2		
13	MISC	Corrosion protection		0.3	12.00	
14	MISC	Pre- and post-repair scan			95.00	

Brightwater Collision & Paint - Estimate BW-26-0419 - page 2 of 2

Summary	Amount
Parts	\$794.05
Body labor 7.4 hrs @ \$62.00	\$458.80
Paint labor 7.0 hrs @ \$62.00	\$434.00
Paint supplies 7.0 hrs @ \$44.00	\$308.00
Hazardous waste disposal	\$6.00
Subtotal	\$2,000.85
Sales tax 7.5% on parts and materials	\$82.65
GRAND TOTAL	\$2,083.50

Notes: Vehicle drivable. Damage confined to rear bumper system, trunk lid lower edge and rear body panel. No frame or unibody damage observed on lift inspection. Supplement possible after teardown. Prices subject to change. This is a preliminary estimate and not a final invoice.

R. Delacombe

Rufus Delacombe, Estimator